

Product Safety Recall

EGR Mitsubishi Triton Canopy

Serial numbers (YYMMDD) 180522 - 210219



Sold by Mitsubishi Australia, Oakmoore Pty Ltd t/as EGR Group and other vehicle accessory retailers between 22 May 2018 and 19 February 2021

Defect The light fitting or pin switch inside the canopy may have been incorrectly assembled.

Hazard If the switch is in the "door" position, there is a risk of an electrical fire inside the canopy, increasing the risk of injury or property damage.

This could occur even when the vehicle is switched off.

What to do Consumers should check the brand and serial number of their canopy to determine if they are affected by this recall. Affected vehicles need to be parked in an open space and away from flammable materials and structures, i.e. not in a garage.

Consumers should contact the place of purchase to organise an appointment to have the light fitting repaired, free of charge.

Contact details Consumers can contact Oakmoore Pty Ltd t/as EGR Group on 1300 320 338 or <https://www.egrgroup.com/contact.html>

**See productsafety.gov.au for
Australian product recall information**